**Format II**

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Aug' 2024
Year: 2024

| Sl. No. | Location Of Accident t and Details Of Victim | Date of occurrence | Type of accident | Cause of accident | Findings of CEI/EI /AEI | Remedies suggested by CEI/EI /AEI in various cases | Whether the remedy suggested is complied | Action taken to avoid recurrence of such accidents | Amount paid as compensa Tion |
|---|---|---|---|---|---|---|---|---|---|
| 1 | An employee was doing maintenance work at Ghonda grid when he suffered injury on his left hand finger while fixing the belt of drilling machine. | 29.06.2024 | Non-Fatal (Employee) | Based on site inspection, probable cause is Carelessnes of ALM | NA | Will be taken based on internal report | NA, as internal report is awaited | NA | NA |
| 2 | A lady got electrocuted at service road C-1 Yamuna Vihar near Moral Hospital from PWD street light pole. This PWD street light pole maintained and owned by PWD.. | 13.07.2024 | Public (Fatal) | Based on site inspection, probable cause is Interference with BYPL network | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| 3 | A person got electrocuted at Gali No. 6 Shahid Bhagat Singh Colony from an illegally hanged wire by consumer on MTNL pole at energy meter no. 35635533. The wire was being used for construction work and person got electrocuted while making connection of water pump inside the construction site.. | 24.07.2024 | Public (Fatal) | Based on site inspection, probable cause is Consumer internal wiring | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| 4 | A person found dead in jhuggi made of tin at Jhuggi nos. C 61/33, Shera Wali market Sadar Bazar Delhi-6 . Deceased was illegally taking power supply from the internal wiring of the adjacent consumer (meter no 2515470). The premises where accident occurred was not BYPL consumer. | 24.07.2024 | Public (Fatal) | Based on site inspection, probable cause is Consumer internal wiring | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| 5 | One lady got electric shock while cleaning her house with broom at 12/158 Geeta Colony. Electrical Inspector inspection is yet to be conducted. | 26.07.2024 | Public (Fatal) | Based on site inspection, leakage current observed from MCD Street Light | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| 6 | One cow got electrocuted due to current leakage on pole no. MVRZ562 in front of dispensary gate Pratap Nagar Mayur Vihar, Delhi. The leakage was coming from open joints of the street light wire. This pole is maintained by MCD. | 01.08.2024 | Animal (Fatal) | Based on site inspection, leakage current observed from MCD Street Light | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| 7 | A PCR complaint vide no. 24081200465 was received at 9:52 AM. LM Subhash & Mahendra reached at Mandoli Kiosk s/stn and switched off the power supply and then reached site immediately and found that a man approx. 50 years old was found lying unconscious on roof of temple. LM also found that 11 KV saboli OH passing through roof of this temple. | 12.08.2024 | Public (Fatal) | Based on site inspection, probable cause is unauthorised construction | Report awaited | Will be taken based on EI report if applicable. | NA, as report from EI is awaited | NA | NA |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

(Signature of the Licensee)