Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Nov' 2023
Year: 2023

Sl. No.	Location Of Accident t and Details Of Victim	Date of occurre nce	Type of acciden t	Cause of accide nt	Findings of CEI/EI /AEI	Remedies sugges ted by CEI/EI /AEI in various cases	Whether the remedy sugges ted is compli e d	Action taken to avoid recurre n ce of such acciden t S	Amount paid as compens a Tion
1	Location: Bhagwanpur Kheda S/Stn.No.1, GT Road A kid was playing near Bhagwanpur Kheda S/Stn.No.1 and he went near to the substation to search ball and suffered flash there.	25.04.2023	Non- Fatal (Public)	-	-	-	-	-	-
2	Location: 1/3-B, Kh. No. 14/9/2, Gali no.1, Ram Mohalla, NR- school, Johripur, Delhi-1100941/3-B, Kh. No. 14/9/2, A girl child, Kavya got injured as a Chinese metallic thread fell on the first floor's metallic railing of her premises and HVDS Network .She was trying to withdraw the Chinese manja/ thread from the railing and Chinese metallic Manja touched the HVDS live network and she got injured due to spark.	21.05.2023	Non- Fatal (Public)	-	-	-	-	-	-
3	Mr. Bhavesh (M/s Denson) got injured during digging work & identifying 11kV cable. His tool (shovel) slipped from stone and minor flash occurred.	04.08.2023	Non- Fatal (Employe e)	-	-	-	-	-	-
4	A child (13 years) touched HVDS DT fuse and got electrocuted	05.08.2023	Non- Fatal (Public)	-	-	-	-	-	-
5	At 13:39 PM a complaint of no power in the area was received at D Block Gamri sub station. LM Kashi Ram and ALM Shiv Kumar and they reached the site and they found that a jumper of IGMS got burnt. They put off the supply through LTACB and repaired the jumper. During the restoring the supply through LTACB a flash occurred and both the team members received the flash on the face hand and upper part of the chest. At the time of flash both local and incomer got tripped.	13.08.2023	Non- Fatal (Employe e)	-	-	-	-	-	-
6	A PCR Complaint no. 23091501469 was received at 11:31 a.m regarding pole broken at the address: Jama Masjid, Gate no.5. When the streetlight team arrived at the site to inspect the pole, they discovered that the base of the iron pole had corroded & it was a Steel tubular pole (Iron pole) with double hang without any fitting & St. light network. Additionally, it was brought to our attention by the Police Chowki that two individuals on a motorcycle were injured and have been admitted to LNJP Hospital.	15.09.2023	Non- Fatal (Public)						

(Signature of the Licensee)