Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Mar' 2025
Year: 2025

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI /AEI	Remedies suggested by CEI/EI /AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	An employee was doing maintenance work at Ghonda grid when he suffered injury on his left hand finger while fixing the belt of drilling machine.	29.06.2024	Non-Fatal (Employee)	Based on site inspection, probable cause is Carelessnes of ALM	NA	Will be taken based on internal report	NA, as internal report is awaited	NA	NA
2	A lady got electrocuted at service road C-1 Yamuna Vihar near Moral Hospital from PWD street light pole. This PWD street light pole maintained and owned by PWD..	13.07.2024	Public (Fatal)	Based on site inspection, probable cause is Interference with BYPL network	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
3	A person got electrocuted at Gali No. 6 Shahid Bhagat Singh Colony from an illegally hanged wire by consumer on MTNL pole at energy meter no. 35635533. The wire was being used for construction work and person got electrocuted while making connection of water pump inside the construction site..	24.07.2024	Public (Fatal)	Based on site inspection, probable cause is Consumer internal wiring	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
4	A person found dead in jhuggi made of tin at Jhuggi nos. C 61/33, Shera Wali market Sadar Bazar Delhi-6 . Deceased was illegally taking power supply from the internal wiring of the adjacent consumer (meter no 2515470). The premises where accident occurred was not BYPL consumer.	24.07.2024	Public (Fatal)	Based on site inspection, probable cause is Consumer internal wiring	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
5	One lady got electric shock while cleaning her house with broom at 12/158 Geeta Colony. Electrical Inspector inspection is yet to be conducted.	26.07.2024	Public (Fatal)	Based on site inspection, leakage current observed from MCD Street Light	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
6	One cow got electrocuted due to current leakage on pole no. MVRZ562 in front of dispensary gate Pratap Nagar Mayur Vihar, Delhi. The leakage was coming from open joints of the street light wire. This pole is maintained by MCD.	01.08.2024	Animal (Fatal)	Based on site inspection, leakage current observed from MCD Street Light	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
7	A PCR complaint vide no. 24081200465 was received at 9:52 AM. LM Subhash & Mahendra reached at Mandoli Kiosk s/stn and switched off the power supply and then reached site immediately and found that a man approx. 50 years old was found lying unconscious on roof of temple. LM also found that 11 KV saboli OH passing through roof of this temple.	12.08.2024	Public (Fatal)	Based on site inspection, probable cause is unauthorised construction	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
8	At 19:09pm a PCR complaint received for current leakage at Naiwala Karol Bagh in high mast light. Lineman reached the site and observed that a person got electric shock. The high mast belongs to MCD.	10.09.2024	Public (Fatal)	Based on site inspection, leakage current observed from MCD Street Light	Report awaited	Will be taken based on EI report if applicable.	NA, as report from EI is awaited	NA	NA
9	An 11 kV feeder Seelampur grid to Maujpur-2 tripped at 09:48 pm while attending the breakdown, one lineman Sh.Jagdeesh met with a minor accident.	16.09.2024	Employee (Non-Fatal)	Based on site inspection, probable cause is Carelessness of Lineman	NA	Will be taken based on internal report	NA, as internal report is awaited	NA	NA
10	AMC Lineman employee of M/S Spark Utility Services Pvt Ltd Emp No SPK1110 working in MMG-MVR 1&2 suffered injury at about 5.30 P.M during meter installation activity.	27.01.2025	Employee (Non-Fatal)	Based on site inspection, probable cause is Carelessness of Lineman	NA	Will be taken based on internal report	NA, as internal report is awaited	NA	NA
11	AMC Lineman employee of lineman of M/s A2Z AMC got electric shock during performing PM in HVDS at Shiv Vihar Ph- 10 B&C block.	10.02.2025	Employee (Non-Fatal)	Based on site inspection, probable cause is Carelessness of Lineman	NA	Will be taken based on internal report	NA, as internal report is awaited	NA	NA

(Signature of the Licensee)