Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Feb' 2024
Year: 2024

Sl. No.	Location Of Accident t and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI /AEI	Remedies suggested by CEI/EI /AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	Location: Bhagwanpur Kheda S/Stn.No.1, GT Road A kid was playing near Bhagwanpur Kheda S/Stn.No.1 and he went near to the substation to search ball and suffered flash there.	25.04.2023	Non-Fatal (Public)	-	-	-	-	-	-
2	Location: 1/3-B, Kh. No. 14/9/2, Gali no.1, Ram Mohalla, NR- school, Johripur, Delhi-1100941/3-B, Kh. No. 14/9/2, A girl child, Kavya got injured as a Chinese metallic thread fell on the first floor's metallic railing of her premises and HVDS Network .She was trying to withdraw the Chinese manja/ thread from the railing and Chinese metallic Manja touched the HVDS live network and she got injured due to spark.	21.05.2023	Non-Fatal (Public)	-	-	-	-	-	-
3	Mr. Bhavesh (M/s Denson) got injured during digging work & identifying 11kV cable. His tool (shovel) slipped from stone and minor flash occurred.	04.08.2023	Non-Fatal (Employee)	-	-	-	-	-	-
4	A child (13 years) touched HVDS DT fuse and got electrocuted	05.08.2023	Non-Fatal (Public)	-	-	-	-	-	-
5	At 13:39 PM a complaint of no power in the area was received at D Block Gamri sub station. LM Kashi Ram and ALM Shiv Kumar and they reached the site and they found that a jumper of IGMS got burnt. They put off the supply through LTACB and repaired the jumper. During the restoring the supply through LTACB a flash occurred and both the team members received the flash on the face hand and upper part of the chest. At the time of flash both local and incomer got tripped.	13.08.2023	Non-Fatal (Employee)	-	-	-	-	-	-
6	A PCR Complaint no. 23091501469 was received at 11:31 a.m regarding pole broken at the address: Jama Masjid, Gate no.5. When the streetlight team arrived at the site to inspect the pole, they discovered that the base of the iron pole had corroded & it was a Steel tubular pole (Iron pole) with double hang without any fitting & St. light network. Additionally, it was brought to our attention by the Police Chowki that two individuals on a motorcycle were injured and have been admitted to LNJP Hospital.	15.09.2023	Non-Fatal (Public)	-	-	-	-	-	-
7	Complaint received at 12:25 Hours on dated 13/12/2023, lineman Kishor reached site and found supply ok. As per neighbors a lady named Soni aged around 30 years got non fatally electrocuted while trying to pull up curtain rod from ground floor to first floor through the window.	13.12.2023	Non-Fatal (Public)	-	-	-	-	-	-
8	3 Phase DB installation work is carried out by RP Traders under the scheme no PN22MS4015. Today work is assigned in West Patel Nagar 22 Block substation at pole no PNRE569 in West Patel Nagar. Sh Rajesh Mukhiya L/M from RP Traders was working on this pole with all necessary PPE . During work he was slipped from the ladder and he got wounds.	06.02.2024	Non-Fatal (Employee)						
9	"LM Sh Rajiveer singh got injured on dated 10 feb 2024 09:15 AM during repairing of HVDS 3 Phase HTAB cable at Amar Vihar Nala Road Karawal Nagar near prem vihar puliya . He was isolating/opening the faulty portion of 3 phase HTAB at the top of pole and meanwhile unfortunately same HVDS pole Y-671 got broken and he fall down ."	10.02.2024	Non-Fatal (Employee)						

(Signature of the Licensee)