

Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Sep-17
Year: 2017

Sl. No.	Location of accident and details of victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI/AEI	Remedies suggested by CEI/EI/AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	4.5 pusta. Div- KWN Victim: Lucky (8yrs old)	23 SEP 17	NON FATAL	ENCROACHMENT	NA				

(Signature of the Licensee)