Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Jun' 2024
Year: 2024

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI /AEI	Remedies suggested by CEI/EI /AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	An employee was doing maintenance work at Ghonda grid when he suffered injury on his left hand finger while fixing the belt of drilling machine.	29.06.2024	Non- Fatal (Employee)	-	-	-	-	-	-

(Signature of the Licensee)