Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: May' 2023
Year: 2023

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI /AEI	Remedies suggested by CEI/EI /AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	Location: Bhagwanpur Kheda S/Stn.No.1, GT Road A kid was playing near Bhagwanpur Kheda S/Stn.No.1 and he went near to the substation to search ball and suffered flash there.	25.04.2023	Non- Fatal (Public)	-	-	-	-	-	-
2	Location: 1/3-B, Kh. No. 14/9/2, Gali no.1, Ram Mohalla, NR- school, Johripur, Delhi-1100941/3-B, Kh. No. 14/9/2, A girl child, Kavya got injured as a Chinese metallic thread fell on the first floor's metallic railing of her premises and HVDS Network .She was trying to withdraw the Chinese manja/ thread from the railing and Chinese metallic Manja touched the HVDS live network and she got injured due to spark.	21.05.2023	Non- Fatal (Public)	-	-	-	-	-	-