Format II

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Apr’ 2023
Year: 2023

Sl. No.	Location Of Accident and Details Of Victim	Date of occurrence	Type of accident	Cause of accident	Findings of CEI/EI /AEI	Remedies suggested by CEI/EI /AEI in various cases	Whether the remedy suggested is complied	Action taken to avoid recurrence of such accidents	Amount paid as compensation
1	Location: Bhagwanpur Kheda S/Stn.No.1, GT Road A kid was playing near Bhagwanpur Kheda S/Stn.No.1 and he went near to the substation to search ball and suffered flash there.	25.04.2023	Non- Fatal (Employee)	-	-	-	-	-	-

(Signature of the Licensee)