**Format II**

Action taken report for safety measures complied for the accidents occurred

Name of Company: BSES YAMUNA POWER LTD, NEW DELHI
Period of Report: Jun’ 2023
Year: 2023

| Sl. No. | Location Of Accident and Details Of Victim | Date of occurrence | Type of accident | Cause of accident | Findings of CEI/EI/AEI | Remedies suggested by CEI/EI/AEI in various cases | Whether the remedy suggested is complied | Action taken to avoid recurrence of such accidentS | Amount paid as compensa Tion |
|---|---|---|---|---|---|---|---|---|---|
| 1 | Location: Bhagwanpur Kheda S/Stn.No.1, GT Road A kid was playing near Bhagwanpur Kheda S/Stn.No.1 and he went near to the substation to search ball and suffered flash there. | 25.04.2023 | Non- Fatal (Public) | - | - | - | - | - | - |
| 2 | Location: 1/3-B, Kh. No. 14/9/2, Gali no.1, Ram Mohalla, NR- school, Johripur, Delhi-1100941/3-B, Kh. No. 14/9/2, A girl child, Kavya got injured as a Chinese metallic thread fell on the first floor’s metallic railing of her premises and HVDS Network .She was trying to withdraw the Chinese manja/ thread from the railing and Chinese metallic Manja touched the HVDS live network and she got injured due to spark. | 21.05.2023 | Non- Fatal (Public) | - | - | - | - | - | - |